



Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

April 18, 1957

BULLETIN NO. 142

TO: ALL DISTRIBUTING OFFICE SERVICE PERSONNEL

SUBJECT: Model "H" Title Rack

We have received some comments concerning the tightness of the title racks in the Model "H".

The title racks are held in place by spring clips, one along the side and one at the bottom of each rack. We intentionally set these to hold the title racks firmly so that they will not come loose during shipment.

On location, of course, the title racks need not be held so securely. It is a simple task to relieve some of the pressure by bending the springs and, especially the bottom springs and clips.

APPLICATIONS ENGINEERING

CLB/hc