



# Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

January 3, 1958

BULLETIN NO. 158

TO: All Distributing Office Service Personnel

SUBJECT: Adjustment of F-3465 Reset Switch

The record changer service manual describes the proper positioning of the reset switches as follows:

"The switch must open .010 inch when the reset lever is pushed manually at the solenoid end until the tip of the lever touches the face of the pin wheel."

If the lever is pulled against the pin wheel from the outer end of the lever, these same conditions will not be met. In this case the contact gap will be less than .010 or may not open at all.

If the switch blades need adjustment, the individual blades may be bent to meet the following conditions.

1. The long blade must bear against the short blade with a force of 10 to 30 grams.
2. When the long blade is held away from the short blade, the short blade must bear against the stiffener blade with a force of 30 to 50 grams.

APPLICATIONS ENGINEERING

/hr